

Maintenance	St Martin's	Desford	Leicestershire	LE9 9GR	Anglican	II*	Structural and roof repairs	£ 3,000
Maintenance	St Michael's	Stoney Stanton	Leicestershire	LE9 4TH	Anglican	II*	Raking out of old mortar and re-pointing of the stonework	£ 2,595
Maintenance	St Andrew	Barrow upon Humber	Lincolnshire	DN39 6SE	Anglican	I	Death Watch beetle treatment to tower floor. Replacement of collapsing choir stall floors.	£ 2,500
Maintenance	All Saints	Croydon, Royston	Hertfordshire	SG8 0DL	Anglican	II*	Repairs to the nave roof - ridge, verge and flashings; Repairs to the tower/nave abutment; Chancel gable capping;	£ 1,700
Maintenance	St Andrew	Soham	Cambridgeshire	CB7 5ED	Anglican	I	Repairs to doors.	£ 1,214
Maintenance	St Helen	Durham	Durham	DH6 4PT	Anglican	I	To remove a silicone-based coating and cement patching from	£ 3,000

							the inside of the chancel walls	
Maintenance	St Thomas a Beckett Farlam	Nr Brampton	Cumbria	CA8 1JL	Anglican	II	Patch and repair work to the chancel, kitchen and vestry roof	£ 512
Maintenance	St Marys	Mellor	Lancashire	BB2 7JE	Anglican	II	Repairs to roof	£ 2,260
Maintenance	Shrine Church of Saint Walburge	Preston	Lancashire	PR2 2QE	Roman Catholic	I	Repair dry rot and address cause	£ 3,000
Maintenance	St Philip & St Paul with Wesley	Southport	Merseyside	PR8 6QF	Anglican	II	Repairs to clerestory windows and surrounding stonework	£ 3,000
Maintenance	St John	Millom	Cumbria	LA19 5YW	Anglican	II*	Investigate existing drains and below ground conditions, replacement of inadequate drains and gullies to ensure water is directed away from the building and address	£ 2,500

							standing water issues at the base of walls. Repairs to damaged rainwater goods.	
Maintenance	St Paul's	Ballygawley	Tyrone	BT70 1TA	Anglican	B	Fix the floor of the bell tower	£ 600
Maintenance	St Dunstan's	Monks Risborough	Buckinghamshire	HP27 9JE	Anglican	I	Repairs to the stonework	£ 3,000
Maintenance	St Paul	Cheltenham	Gloucestershire	GL504EZ	Anglican	II*	Repairs and maintenance to roof, flashings and gulleys.	£ 1,250
Maintenance	St John the Evangelist	Luton	Devon	TQ13 0BN	Anglican	II	Replace all guttering and addition of new downpipes	£ 3,000
Maintenance	Tedstone, St James	Bromyard	Herefordshire	HR7 4PT	Anglican	II*	Repair floor and walls damaged by dry rot.	£ 3,000
Maintenance	St Michael & All Angels	Little Witley	Worcestershire	WR6 6LP	Anglican	II	Removing & restoring kneeler & all oak floorboards, decaying bearers, oak	£ 1,885

							flooring, lifting sunken tiles, cleaning off original adhesive & grout, filling voids, relaying tiles & regrouting.	
Maintenance	St John	Wall	Staffordshire	WS14 0AS	Anglican	II	Repair of a few open joints to stonework and some spalling mullions to windows	£ 1,850
Maintenance	St Oswald	Leyburn	North Yorkshire	DL8 3HG	Anglican	I	Essential repairs to walls of accessible toilet to prevent worsening damp.	£ 1,900
Maintenance	St Edward King and Confessor	Leeds	West Yorkshire	LS23 6HU	Roman Catholic	II	Asbestos removal	£ 3,000
Maintenance	St Matthew	Sheffield	South Yorkshire	S1 4FT	Anglican	II	Remedial maintenance work to the East elevation of the church	£ 2,700

							to stop water ingress	
Maintenance	Church of the Ascension	near York	North Yorkshire	YO26 8AR	Anglican	II*	Stonework replacement to two aisle windows which are severely weathered	£ 3,000
Maintenance	St Martin's	Doncaster	Yorkshire	DN6 9BH	Anglican	I	Replacement of west tower louvre in oak and re-used leadwork to prevent future water damage	£ 600